OHIO HISTORIC	<u> </u>	/ENTORY JUNE 19	Columbus, Ohio 43211	
1. No. /7 2. County	1	ent Name(s) No. 27 ("Johnny Cake Lock")		13
Summit		r Name(s)		
3. Location of Negatives OHS				
6. Specific Location		16. Thematic Category	28. No. of Stories	Ŋ
on private road approx.		F, H, I 17. Date(s) or Period	29. Basement? Yes ☐ No ☐	Summi
ft. east of intersection Riverview & Everett Rds.		1825-1827	30. Foundation Material	nit
7. City or Town If Rural, Township & Vicinity		18. Style or Design	31. Wall Construction	
Everett 8. Site Plan with North Arrow EVERETT RD.		19. Architect or Engineer	load-bearing masonry	
		20. Contractor or Builder	32. Roof Type & Material	
		20. Contractor or builder	33. No. of Bays	-
		21. Original Use, if apparent canal lock	Front Side 34. Wall Treatment	Lock
		22. Present Use	cut stone/concrete	\mathbf{z}
TRUNC RW	N		35. Plan Shape rectangle	ō.
9. Coordinates Lat. Long.		23. Ownership Public 2©X Private □	36. Changes Addition ☐ (Explain Altered ☑	27
		24. Owner's Name & Address, if known	in #42) Moved □ 37. Condition	_
U.T.M. Reference		Akron Metro. Park District	xixingrizer	ئے
17 452140 45612	40	976 Treaty Line Rd., Akron	xxxxxx fair	앍
Zone Easting Northing 10. Site □ Struc	ture 🛎	25. Open to Yes ∑x Public? unrestricted No □	38. Preservation Yes ☐ Underway? No 🕱	ohnny
Building Ob	oject 🗆	26. Local Contact Person or Organization	39. Endangered? Yes □	a
11. On National Yes \(\) 12. Is It Register? No \(\) Eligible?	Yes 🔼 No □	Summit Co. Hist. Soc.	By What? No XX	ake

42. Further Description of Important Features Lock is standard mitered gate type. The lock chamber is 90 feet long by 15 feet wide. Of cut sandstone construction, it was repaired with concrete c. 1905. Both gates are missing. Some water in lock chamber, canal itself is dry south of Peninsula. There is an original piece of hardware--probably the wrought iron collar bearing that held the oak gate post -- in the east lock wall at south end

Yes 🗷

No 🗀

14. District

Potent'l?

13. Part of Estab. Yes

No x

15. Name of Established District

Hist. Dist.?



Public Road?

41. Distance from and

Frontage on Road

Yes ☐ No 🕰

Lock"

43. History and Significance According to tradition, in the spring of 1828 a flood in Furnace Run swept into the canal and stopped navigation. "...the crews and passengers were compelled to live, water-bound, as best they could. They were at last reduced to johnnycake, which constituted their diet for a number of days." Thus the origin of the name for this lock at Everett, a canal stopover then known as 44. Description of Environment and Outbuildings Unionville.

included in "Ohio & Erie Cana 10. Visible from

historic civil engineering

landmark, Ohio Council ASCH

Approx. Acreage: less than 1

In the small residential neighborhood that constitutes the village of Everett.

15. Sources of Information	46.	Prepared by
History of Summit County, ed. William Henry Perrin (Chica, Baskin & Battey Historical Publishers, 1881) n. 5/1	goı	Carol Poh Miller
Baskin & Battey, Historical Publishers, 1881), p. 54	d47	Organization
	7".	Organization
Frank Wilcox, The Ohio Canals, selec. and ed. William A.	L	
McGill (Kent, O.: Kent State University Press, 1969)	48.	Date 49. Revision Date(s)
see esp. p. 21 on lock hardware.	13	/76