OHIO HISTORIC	11/1	/ENTURY	Columbus, Ohio 43211
1. No. /9	i	ent Name(s)	
2. County	Lock	k No. 26 ("Pancake Lock")	
Summit	5. Othe	er Name(s)	
OHS OF Negatives			
6. Specific Location on private road (formerly		16. Thematic Category F, H, I	28. No. of Stories
canal towpath) 0.3 mile no	orth	17. Date(s) or Period 1825-1827	29. Basement? Yes □ No □
of Ira Rd.			30. Foundation Material
7. City or Town If Rural, Township & VITa	/icinity	18. Style or Design	31. Wall Construction
		19. Architect or Engineer	load-bearing masonry
8. Site Plan with North Arrow	<b>9</b> .	20. Contractor or Builder	32. Roof Type & Material
A STATE OF THE STA	,		33. No. of Bays
The sold of the so	A	21. Original Use, if apparent canal lock	Front Side
	T !	22. Present Use	34. Wall Treatment cut stone/concrete
THE IRA RA (AU	1		35. Plan Shape rectangle
	<u> </u>	23. Ownership Public ໕ Private □	36. Changes Addition □ . (Explain Altered 🗹
9. Coordinates	1	24. Owner's Name & Address,	in #42) Moved □
U.T.M. Reference	ļ	State works. Dept. of Public	37. Condition fair
1 7   4 5 1 2 4 0   4 5 5 9 3	00	65 S. Front St., Columbus	XXXXX
Zone Easting Northing		25. Open to Yes ☐	38. Preservation Yes ☐ Underway? No 🔀
	ture XI oject □	,	39. Endangered? Yes □
		26. Local Contact Person or Organization Summit County Hist. Soc.	By What? No ₫
	No □ Yes 🌠	27. Other Surveys in Which included included in "Ohio & Erie Cana	La Walble from Yes
	No	historic civil engineering	Public Road? No 🖾
15. Name of Established District		landmark, Ohio Council ASCE	41. Distance from and Frontage on Road
		Approx. Acreage: less than 1	rionago on rioad
42. Further Description of Important Features  Lock is standard mitered gate type. The lock chamber is			
90 feet long by 15 feet w	wide.	. Of cut sandstone construc-	A
tion, it was repaired wit	th co	oncrete c. 1905, some of which	h Y
has chipped away. Both gin the lock chamber. Loc	gates ck it	s are missing. There is water tself is heavily overgrown	
with thickets.	JAL 1 0	vecti in measify overblown	
Mho name for this look probable devices from an inside the initial to the			
The name for this lock probably derives from an incident similar to that at "Johnny Cake Lock," 1½ miles to the north at Everett.			

44. Description of Environment and Outbuildings

Almost hidden in the thickets in a much-overgrown portion of the canal. The road along which it is located (formerly the canal towpath) leads to a private residence of recent date.

45 Sources of Information

Canal Society of Ohio, Towpaths, Sesquicentennial Issue No. 1: 150 Years of Ohio's Canals (n.p., 1975).

Charles Asa Post, The Cuyahoga: The Crooked River That Made a City Great (Privately printed, 1941), p. 37. 46. Prepared by Carol Poh Miller

47. Organization

48. Date 49. Revision Date(s) 4/76